Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	50	(("5973472") or ("5235265") or ("4762463") or ("4622513") or ("4517498") or ("5570278") or ("5796595") or ("5991171") or ("4253053") or ("4464618") or ("4567420") or ("4764714") or ("5276392") or ("5434767") or ("5636106") or ("4391570") or ("5350994") or ("4784580") or ("5631543") or ("5394893") or ("5440890") or ("5528908") or ("5703457") or ("5784800") or ("6167588") or ("4479115") or ("4528898") or ("4962734") or ("5350281") or ("5840103") or ("6010561") or ("6093990") or ("6231649") or ("5751530") or ("5856904") or ("6302640") or ("4486699") or ("4937513") or ("4463303") or ("4465962") or ("4476422") or ("4555654") or ("4856182") or ("4958051") or ("5192887") or ("5212435") or ("5421399") or ("5689164") or ("4253052") or ("4808868")).PN.	USPAT	OR	OFF	2005/05/02 10:35
L2	5	1 and (airflow near2 block$).detd.	USPAT	OR	OFF	2005/05/02 11:43
L3	1	2 and (alarm$ or warn$ or alert?$).detd.	USPAT	OR	OFF	2005/05/02 10:46
L4	1	2 and (alarm$ or warn$ or alert$).detd.	USPAT	OR	OFF	2005/05/02 11:04
L5	1	4 and (sens$ or detect$ or monitor$).detd.	USPAT	OR	OFF	2005/05/02 11:07
L6	1	4 and (block$ and (alarm$ or warn$ or alert$)).detd.	USPAT	OR	OFF	2005/05/02 11:06
L7	6	1 and (block$ and (alarm$ or warn$ or alert$)).detd.	USPAT	OR	OFF	2005/05/02 11:06
L8	5	7 and (sens$ or detect$ or monitor$).detd.	USPAT	OR	OFF	2005/05/02 11:16
L9	5	8 and (ac or alternat$ or current).detd.	USPAT	OR	OFF	2005/05/02 11:25
L10	4	9 and (temperature or heat or thermal).detd.	USPAT	OR	OFF	2005/05/02 11:26
L11	3	10 and ((compar$ or difference) with current$1).detd.	USPAT	OR	OFF	2005/05/02 11:38
L12	3	11 and (winding$1 or coil$1 or transformer$1).detd.	USPAT	OR	OFF	2005/05/02 11:33

L13	5	((airflow or (air near (passageway or passage))) with block$ with (alarm$ or warn$ or alert$)).detd.	USPAT	OR	OFF	2005/05/02 11:36
L14	2	13 and (current or amps or amper$).detd.	USPAT	OR	OFF	2005/05/02 11:36
L15	144	((airflow or (air near (passageway or passage)) or air) with block$ with (alarm$ or warn$ or alert$)).detd.	USPAT	OR	OFF	2005/05/02 11:59
L16	0	14 and (current same (transformer$1 or winding$1 or coil$1)).detd.	USPAT	OR	OFF	2005/05/02 11:37
L17	9	15 and (current same (transformer$1 or winding$1 or coil$1)).detd.	USPAT	OR	OFF	2005/05/02 11:38
L18	0	17 and ((compar$ or difference) with current$1).detd.	USPAT	OR	OFF	2005/05/02 11:41
L19	4	15 and ((compar$ or difference) with current$1).detd.	USPAT	OR	OFF	2005/05/02 11:41
L20	2	2 and current.detd.	USPAT	OR	OFF	2005/05/02 11:44
L21	8	("5528908").URPN.	USPAT	OR	OFF	2005/05/02 11:44
L22	6	("5440890").URPN.	USPAT	OR	OFF	2005/05/02 11:45
L23	10	("5350281").URPN.	USPAT	OR	OFF	2005/05/02 11:45
L24	15	("4962734").URPN.	USPAT	OR	OFF	2005/05/02 11:45
L25	6	(21 or 22 or 23 or 24) and (current and block$).detd.	USPAT	OR	OFF	2005/05/02 11:58
L26	0	("split-capacitor" and "singl-phase").detd.	USPAT	OR	OFF	2005/05/02 11:58
L27	24	("split-capacitor" or "singl-phase").detd.	USPAT	OR	OFF	2005/05/02 11:58
L28	4	27 and fan.detd.	USPAT	OR	OFF	2005/05/02 12:00
L29	0	15 and 27	USPAT	OR	OFF	2005/05/02 11:59
L30	10	27 and block$.detd.	USPAT	OR	OFF	2005/05/02 11:59